

Software update information

Software update 9/2010 (MX-1.12.0)

File name: UPD01000.bin

Content

The 9/2010 software update improves the speed and stability of music playback from a USB drive that is connected to the USB audio interface in the centre armrest and contains multiple playlists.

Supported devices

The software update improves the compatibility of the following devices:

- ▷ All USB media

Conditions

The software update is only available for certain vehicles equipped with a USB audio interface (option code 6FL).

In these vehicles, the menu option "Software update" is provided in the main menu under "Settings". Further information is provided in the Owner's Handbook for Vehicle under Software Update.

Supported vehicles

The software update is available for the following vehicles:

- ▷ BMW 7 Series Saloon with production dates 03/2010 – 08/2010
- ▷ BMW 3 Series Coupé/Convertible with iDrive and production dates 03/2010 – 08/2010
- ▷ BMW 5 Series Touring with production dates 06/2010 – 08/2010

Only vehicles from selected European markets will be supported in the case of vehicles with production dates 03/2010 – 08/2010. The software update is not required for vehicles with production dates later than 09/2010.

Installation

Installation of the software update requires agreement with the terms and conditions of use. For further information, see www.bmw.com/update.

For the purposes of installation, save the software update file in the main directory of a USB drive. Observe the additional instructions in the Owner's Handbook under Software Update.

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":

- ▷ MX-1.12.0

Notes

Once the software has been updated, the software in the vehicle is restarted and data transferred from the USB drive resynchronised where necessary. Wait a few minutes until the USB drive is operational again.

Tracks or playlists played before the software update must be selected again. This is also required when the previous version of the software is restored using "Restore previous version".

© 2010 Bayerische Motoren Werke
Aktiengesellschaft
Munich, Germany
Readme_UPD01000_ENG.pdf